
# G-Force GFQ5000 QL50 Shank

### **Hammer Service Log**


### **Wear Sleeve / Piston Clearance**

Part		New Dimension	Discard Clearance	
Wear Sleeve	Α	3.74"	greater then or equal to 0.040"	
Piston OD	В	3.736"	greater than or equal to 0.010"	




## **Inner Cylinder / Piston Clearance**

Part		New Dimension	Discard Clearance
Cylinder ID	С	3.13"	greater than or equal to 0.010"
Piston OD	D	3.126"	greater than or equal to 0.010"



### **Distributor Probe / Piston ID Clearance**

Part	N	lew Dimension	Discard Clearance
Distributor Probe OD	F	1.181"	greater than or equal to 0.010"
Piston ID		1.194"	greater than or equal to 0.010"



#### **External Wear**

Description	Wear Limit
Wear Sleeve Reverse Dimension	4.252"
Wear Sleeve Discard Dimension	4.134"

#### NOTE:

- 1. If no evidence of significant air pressure drop or if wear sleeve is wearing evenly on the top and bottom end, recommendation is to not reverse wear sleeve.
- 2. Chuck should be replaced when wear transfers to wear sleeve.