
# G-Force GFQ8000 QL80 Shank

### **Hammer Service Log**


### **Wear Sleeve / Piston Clearance**

Part		New Dimension	Discard Clearance
Wear Sleeve	Α	5.984"	greater then or equal to 0.040"
Piston OD	В	5.98"	greater than or equal to 0.010"




## **Inner Cylinder / Piston Clearance**

Part		New Dimension	Discard Clearance
Cylinder ID	С	5.197"	greater then or equal to 0.010"
Piston OD	D	5.192"	greater than or equal to 0.010"



### **Distributor Probe / Piston ID Clearance**

Part		lew Dimension	Discard Clearance	
Distributor Probe OD	F	1.803"	greater then or equal to 0.010"	
Piston ID		1.811"	greater than or equal to 0.010"	



### **External Wear**

Description	Wear Limit
Wear Sleeve Reverse Dimension	6.811"
Wear Sleeve Discard Dimension	6.693"

#### NOTE:

- 1. If no evidence of significant air pressure drop or if wear sleeve is wearing evenly on the top and bottom end, recommendation is to not reverse wear sleeve.
- 2. Chuck should be replaced when wear transfers to wear sleeve.